

Industry: Plating

Application: Part Washing

Product Descriptions: 1/4" NF10-90

Situation: A plating company was having trouble with cross-over contamination in their rinsing bath since they use the same rinsing/washing bath for several different plating processes. The current rinsing bath is a large rectangular tub with standing fluid that the parts are lowered into.

BETE's solution: BETE Application Engineers recommended the standing fluid be replaced with two headers with NF fan nozzles mounted on them. The headers created a horizontal water wall much like the surface of the standing fluid. As the parts were lowered through this water wall they would be rinsed. The cross-contamination from different processes is eliminated because there is no longer any standing fluid.

Technical Questions?

Please contact:
Applications Engineering
(appeng@bete.com)
413-772-0846
App#071666

